

Annexure -I

Sample Report

Measurement Report

Date: 27.07.07
Time: 11:31:35

Component : Casing 500MW

Drg. No : 0-10307-41007

Project Name : Raichur

Machine: CNC Horizontal Borer 160 (Model name/Layout number of machine)

* Note: '0' in Error denotes "Measured Values are within tolerance" *

Description	Nom. Size	Measured Value	Dev.from Nom.Size	Tol. upper (+)	Tol. lower (-)	Error (Out-Tol)
SLOTWIDTH:	40	40.0345	0.0345	0	-0.05	0.0345
SLOTDEPTH:	24.6	24.5548	-0.0451	0	-0.13	0
GROOVEWIDTH:	39	39.0755	0.0755	0.1	-0.1	0
-----	---	----	---	---	---	---
-----	---	----	---	---	---	---
-----	---	----	---	---	---	---
MAIN INNER BORE	121.98	122.1065	0.1265	0.04	-0.02	0.0865
OUTER TAPER ANGLE:	1.475	1.4943	0.0193	0.05	-0.05	0
COUNTER BORE: (DET-1)	34.847	34.9773	0.1303	0.04	-0.02	0.0903

Note:

- The Nominal size means the nominal value as mentioned in the drawing without application of any tolerance or any adjustment for mid value.
- The Tolerance values should be specified in Upper and Lower tolerance as mentioned in the drawing and not in any other tolerance band with adjustment.

GUIDELINES FOR MACHINING PROCESS OF END SHIELD (MACHINED)
DRAWING NO. 0-139-37-01006

- General sequence of machining process for End Shield (Machined) drawing no. 0-139-37-01006 is to be followed as per the enclosed process sheets (having 29 operations) during the proving out of machine. However, minor changes in sequence can be made to suit the CNC machine and to increase the productivity of machine.
- Operations, which have been marked “Vendor’s scope” are only to be carried out on the machine during proving out of machine by the Vendor. Remaining operations marked “BHEL’s scope” are to be carried out by BHEL away from machine.
- Machining allowance per surface may be taken as 10 mm (approx.).



18/05/2007

CBOM

18.05.2007

Page 1/32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

1/29 2025 935 ~~0202-0205~~ BHEL SCOPE

NOTE:-I.BLOCK-I ENSURE THAT END SHIELDS RECEIVED FROM BLOCK-II ARE CLEANED, DEFICIENCIES IF ANY, TO BE REMOVED IN BLOCK-I BEFORE M/CING.
II.BEARING OIL INLET PIPE TO BE SUITABLY PLUGGED TO AVOID ENTRY OF CHIPS DURING MACHINING.
MARKING OF UPPER HALF:-

1/29 Continued

- 1.PLACE UPPER HALF OF END SHIELD ON MARKING TABLE WITH ALIGNMENT WEDGES IN BETWEEN KEEPING FLANGE SIDE (H2 SIDE) TOWARDS MARKING TABLE AND SPLIT SURFACE IN VERTICAL PLANE.
- 2.ALIGN THE HALF SHIELD TO MAKE

1/29 Continued

- THE SPLIT SURFACE VERTICAL.
CHECK ITS PERPENDICULARITY TO OTHER SURFACES.
- 3.MARK SPLIT SURFACE TO DIMENSION 55 (SEC. C-C AND B-B).
 - 4.MARK BEARING CENTRE LINE MAINTAINING DIMENSION 140 (SEC. A-A).

1/29 Continued

- 5.MARK REFERENCE AT PLANE FLANGE SIDE (H2 SIDE) AT 470 FROM BEARING C/L (SEC. A-A)
- 6.MARK FOR MACHINING SURFACE FOR FITTING END SHIELD COVER ITEM 13 MAINTAINING DIMENSION 279 FROM BRG. CENTRE LINE (SEC. A-A).
- 7.MARK FOR MACHINING SURFACE 755X535

S GHOSH

S K TANDON

5
10.05.2005



CBOM

18.05.2007

Page 2 / 32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

1/29 Continued

WITH R60 ON OPENING.

8. LOCATE VERTICAL CENTRE LINE

OF THE JOB IN THE MIDDLE OF THE FLANGE SURFACE.
TRANSFER THE CENTRE LINE ALL AROUND.

9. TAKING THE MARKED CENTRE AS REFERENCE, CARRY OUT
CONTROL MARKING ON ALL SURFACES

1/29 Continued

TO BE MACHINED AS SHOWN IN SEC. A-A.

10. CHECK THE AVAILABILITY OF SUFFICIENT MACHINING
ALLOWANCE ON ALL THE SURFACE TO BE MACHINED.
CARRY OUT MANIPULATION

IF MATERIAL IS NOT AVAILABLE ON ANY SURFACE.

11. CLEARLY IDENTIFY MARKING OF VERTICAL CENTRE

1/29 Continued

LINE (ALL AROUND) AND BEARING CENTRE LINE.

INSPECTION-CHECK CONTROL MARKING AND

AVAILABILITY OF MACHINING ALLOWANCE
ON ALL THE SURFACES.

2/29 2035 266

~~10/29~~

~~2035~~

~~266~~

VENDOR SCOPE

ALTERNATIVELY FOLLOW CNC PROGRAMME NUMBER % 6911

, 6921, 6931, 6932, 6941, 6951, 6961, 6971, 6972, 6981,

6982 AND 6991 FOR WOTAN-RAP-6C (1-227) EQUIPMENT

CODE 266 FOR MANUFACTURING THIS

COMPONENT ON CNC MACHINE TOOL. COMPONENT SHALL BE

DULY INSPECTED BY QC AFTER COMPLETION OF OPERATION

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 3/32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

2/29 Continued

1. PLACE UPPER HALF OF END SHIELD ON M/C TABLE WITH PARTING PLANE ON SUPPORTS ON M/C TABLE & WITH BEARING END SHIELD COVER SURFACE TOWARDS M/C SPINDLE. ALIGN AS PER MARKING OF SPLIT SURFACE IN VERTICAL & HORIZONTAL PLANE AND MARKED CENTRE LINES.

2/29 Continued

2. MILL AREA FOR FITTING END SHIELD COVER (ITEM 13) MAINTAINING DIMENSION 279 AS PER MARKING & SEC. A-A.
3. MILL AREA FOR FITTING COVER ITEM 76 (REFER DRG. 01393701005) MAINTAINING DIMENSIONS 535X755 WITH R60 AT

2/29 Continued

CORNERS AS PER MARKING MAINTAINING DEPTH TILL CLEANING ON INNER SIDE OF H2 SIDE PLATE.
INSPECTION- CHECK DIMENSIONS.

3/29 2045 935

BHEL SCOPE

1. PLACE END SHIELD COVER ITEM 13 ON END SHIELD CONCENTRIC AS PER DRG. TRANSFER LOCATION OF 19 HOLES D17.5 (M20) CORRESPONDING TO THE HOLES IN E.S. COVER ITEM 13
2. MATCH MARK E.S. COVER WITH END SHIELD.
S GHOSH S K TANDON

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

3/29 Continued

3. PLACE COVER ITEM 76 ON END SHIELD AS
PER DRG. (REFER DRG. 01393701005). TRANSFER
LOCATION OF 40 HOLES M20 (SEC. A-A)
ON END SHIELD CORRESPONDING TO
THE HOLES IN COVER.

4/29 2045 254

VENDOR SCOPE

1. DRILL, C' SINK AND TAP 19 HOLES
M20 MAINTAINING DEPTH
AS PER DRG. (DRILL DEPTH 35, THREAD DEPTH 28).
2. DRILL, C' SINK, AND TAP 40 HOLES M20
MAINTAINING DEPTH OF HOLES 36
AND DEPTH OF THREAD 28 (SEC. A-A).

4/29 Continued

INSPECTION-CHECK DIMENSIONS.

5/29 2045 934

BHEL SCOPE

1. DEBURR AND CLEAN CONTACT SURFACE OF END SHIELD
FOR END SHIELD COVER ITEM 13 AND COVER ITEM 76.
2. ASSEMBLE END SHIELD COVER ITEM
13 WITH THE HELP OF 19.
BOLTS ITEM 25 AS PER DRG. WITH TECHNOLOGICAL
PACKING 1MM THICK.

R7429.0054 TECH. PACKING

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 5/32

XXX

1

END SHIELD MACHINING

01393701005 00 2

01393701006 00

9250.000

0202-0205

5/29 Continued

INSPECTION-CHECK ASSEMBLY AS PER DRG.

6/29 2035 266 ~~1000~~ ~~1000~~ ~~1000~~ VENDOR SCOPE

ALTERNATIVELY FOLLOW CNC PROGRAMME NUMBER %
FOR OPN.NO. TO FOR MANUFACTURING THIS
COMPONENT ON CNC M/C TOOL. COMPONENT SHALL BE DULY
INSPECTED BY QC AFTER COMPLETION OF OPERATION.
ROUGH MACHINING OF UPPER HALF END SHIELD:-

1. PLACE UPPER HALF ON M/C BED PLATES WITH FLANGE

6/29 Continued

SIDE(H2 SIDE) RESTING ON SUPPORTS AND SPLIT
SURFACE TOWARDS M/C SPINDLE. ALIGN IN
HORIZONTAL AND VERTICAL PLANES AS PER MARKING ON
SPLIT SURFACE AND CLAMP. RECHECK THE ALIGNMENTS
W.R.T MARKING AT THE OTHER
SURFACE AND RE-ALIGN IF NECESSARY.

6/29 Continued

2. PRELIMINARILY MILL SPLIT SURFACE
AS PER THE MARKING LEAVING 0.3MM
ALLOWANCE FOR FINAL MILLING.
3. MILL 2 ALIGNMENT POINTS ON THE
TOP AND BOTTOM OF ONE OF THE VERTICAL
SIDES. LENGTH OF THE MILLED AREA TO BE

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 6

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

6/29 Continued

APPROX 100MM. BOTTOM OF THE TWO
MILLED SURFACES MUST BE EXACTLY IN
THE SAME VERTICAL PLANE. MILLING TO BE
CARRIED OUT WITH THE HELP OF A LARGE DIAMETER
END MILL TO MINIMUM POSSIBLE DEPTH.

4. SIMILARLY MILL TWO MORE ALIGNMENT

6/29 Continued

POINTS ON THE SECOND VERTICAL SIDE.
5. MILL TWO ALIGNMENT POINTS AT
THE TWO ENDS OF THE TOP
HORIZONTAL SIDE BOTTOM OF THESE POINTS
MUST BE EXACTLY IN THE SAME HORIZONTAL PLANE
INSPECTION-CHECK PRELIMINARY MILLING OF SPLIT

6/29 Continued

SURFACE AND ALIGNMENT POINTS.
6. LEAVE THE JOB IN THE
CLAMPED CONDITION ON THE M/C TO CARRYOUT
THE MARKING.(NOT IN CASE OF CNC H. BORER)

7/29 2035 935

~~0202-0205~~

BHEL SCOPE

THE FOLLOWING MARKING MAY BE
CARRIED OUT ON THE HORIZONTAL BORING M/C FOR
BETTER ACCURACY.(NOT IN CASE OF CNC H.BORER)
JOB HAS BEEN LEFT IN THE ALIGNED AND CLAMPED
CONDITION ON THE MACHINE AFTER THE
PREVIOUS OPERATION. FIX CENTRE

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 7/32

XXX

1

END SHIELD MACHINING

01393701005 00 2

01393701006 00

9250.000

0202-0205

7/29 Continued

IN THE M/C SPINDLE FOR
MARKING AND LOCATING DIMENSIONS.

1. MARK 30 HOLES DIA 39 AS PER VIEW-Y
ON THE SPLIT SURFACE OF UPPER HALF.
2. MARK 16 HOLES DIA 33 ON THE SPLIT
SURFACE OF UPPER HALF AS PER VIEW-Y.

7/29 Continued

3. MARK 2 HOLES EACH FOR PINS AS PER SEC. B-B
AND D-D (REFER VIEW Y AND Z).
4. MARK 4 HOLES FOR TAPER PINS AS PER
SEC. C-C AND VIEW-Y.
5. MARK 4 HOLES DIA 22 AS PER VIEW-Y.
6. MARK 2 HOLES DIA 12 AS PER

7/29 Continued

VIEW-Y MAINTAINING DISTANCE 31.

7. MARK AREAS 100X240 WITH R50
AS PER VIEW-Y.

8/29 2035 266

~~1000~~ ~~1000~~ ~~1000~~

VENDOR SCOPE

1. PLACE UPPER HALF ON M/C
BED PLATE WITH SPLIT SURFACE
TOWARDS M/C SPINDLE AND FLANGE
(H2) SIDE RESTING ON SUPPORTS. ALIGN AS PER THE
SPLIT SURFACE AND CLAMP.
2. DRILL THROUGH 30 HOLES D39 AS PER MARKING & VIEW
S GHOSH S K TANDON



CBOM

18.05.2007

Page 8

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

8/29 Continued

-Y. CHAMFER TO 3X45DEG.(REFER NOTE IN ZONE C-9)

3. REVERSE SPOT FACE THESE HOLES TO DIA 82 WITH
DEPTH 2 MM AS PER VIEW-Y.

R2350.0456 R'C'B' TOOL D39
/D82

4. DRILL 16 HOLES DIA 33

THROUGH AS PER MARKING AND VIEW-Y.

R6235.0179 MANDREL D39/D82

5. REVERSE SPOT FACE THESE HOLES DIA 33

8/29 Continued

TO DIA 69 MAINTAINING DEPTH 2 MM AS PER VIEW-Y.

R6300.0775 R'C'B' MANDREL
D33/D69

6. DRILL 2 HOLES DIA 12 AS PER MARKING & VIEW-Y.

7. MILL AREA 100X240 WITH R50

WITH DEPTH 2MM AS PER MARKING(VIEW-Y).

8. GET 2 HOLES M20 MARKED AS PER VIEW-Y.

9. DRILL 2 HOLES DIA 17.5 (M20) TO DEPTH 31

8/29 Continued

10. TAP 2 HOLES TO M20 DRILL DEPTH 23.

11. RESET TO PLACE SPLIT SURFACE ON ROTARY TABLE.

ALIGN AS PER SPLIT SURFACE AND ALIGNMENT POINTS
AND CLAMP, KEEPING HYDROGEN SIDE
TOWARDS M/C SPINDLE.

12. MILL ONE ALIGNMENT POINT

8/29 Continued

IN THE MIDDLE OF BORE DIA 542(REFER DETAIL-V)
WITH THE HELP OF END MILL APPROX DIA 50. CUT TO
BE TAKEN TO DEPTH 2 SO THAT SOME ALLOWANCE
IS LEFT FOR FINISH TURNING DIA 542. MEASURE AND
RECORD THE DISTANCE FROM THE MIDDLE
OF THIS ALIGNMENT POINT TO THE

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 9 / 32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

8/29 Continued

SPLIT SURFACE WITH THE HELP OF MICROMETER.

UNCLAMP AND REMOVE FROM M/C.

INSPECTION-I. CHECK DIMENSION AND FINISH.

II. CHECK AND RECORD THE DISTANCE OF
ALIGNMENT POINT TO THE SPLIT SURFACE

9/29 2035 935



BHEL SCOPE

MARKING OF LOWER HALF:-

1. REPEAT OPERATION NO. 1/29
(EXCEPT SL. NO. 6 & 7) FOR LOWER
HALF END SHIELD ITEM NO. 1
TO CARRYOUT CONTROL MARKING. REFER
DIMENSIONS APPLICABLE FOR LOWER HALF AS PER DRG.

9/29 Continued

2. MARK FOR MILLING AREA 510X400
WITH R125 AT CORNERS (ZONE H-11).
3. MARK FOR MILLING AREA 300X325
WITH R50 AT TWO CORNER
MAINTAINING DISTANCE 240 & 360 (VIEW-N).
4. MARK FOR MILLING AREA 620

9/29 Continued

(310+310)X170 AT THE BOTTOM AS PER DRG.

INSPECTION- CHECK CONTROL MARKING AND
AVAILABILITY OF ALLOWANCE ON ALL SURFACES.

S GHOSH

S K TANDON

5
10.05.2005



CBOM

18.05.2007

Page 10

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

10/29 2035 266

~~XXXXXXXXXX~~

VENDOR SCOPE

NOTE- ALTERNATIVELY FOLLOW CNC PROGRAMME NO. %
 & FOR OPERATION NO. ,
 & FOR MANUFACTURING THIS COMPONENT ON CNC
 M/C TOOL. COMPONENT SHALL BE DULY INSPECTED BY
 Q.C. AFTER COMPLETION OF OPERATION.
 ROUGH MACHINING OF LOWER HALF:-

10/29 Continued

1. REPEAT OPERATION 6/29 TO CARRYOUT ROUGH MACHINING
 OF SPLIT SURFACE (LEAVING 0.3MM ALLOWANCE)
 AND MILLING OF SIX NOS. ALIGNMENT POINTS.
 INSPECTION-CHECK PRELIMINARY MILLING OF SPLIT
 SURFACE AND MILLING OF SIX NOS ALIGNMENT PTS.
2. UNCLAMP & REMOVE FROM M/C.

11/29 2035 935

~~XXXXXXXXXX~~

BHEL SCOPE

1. PLACE LOWER HALF END SHIELD ON TWO NOS.
 EQUAL HEIGHT BOX SUPPORTS. ALIGN TO BRING
 SPLIT SURFACE IN HORIZONTAL PLANE.
2. PLACE UPPER HALF ON LOWER HALF. ALIGN UPPER HALF R7843.0080 CENTRE PUNCH
 AS PER MARKING OF REFERENCE PLANE
 ON FLANGE SIDE (H2 SIDE) AND

11/29 Continued

VERTICAL CENTRE LINE ON UPPER
 HALF COINCIDE WITH THAT OF LOWER
 HALF. CHECK MATCHING OF THE MARKING ALSO.

3. TRANSFER FROM UPPER HALF
 TO LOWER HALF CENTRES AT HOLES
 CORRESPONDING TO 30 HOLES

S GHOSH

S K TANDON

R7845.0740 BUSH D39(1) D33
 (2) D22(3)

5

10.05.2005



CBOM

18.05.2007

Page 11

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

11/29 Continued

DIA 39 AS PER VIEW Y (SEE TR 3)

4. TRANSFER LOCATION OF 16 HOLES DIA 33
AS PER VIEW-Y (SEE TR-3).

5. TRANSFER LOCATION OF 4
HOLES DIA 22 AS PER VIEW-Y.

INSPECTION-CHECK ALIGNMENT OF UPPER

11/29 Continued

HALF W.R.T. LOWER HALF AND
TRANSFER THE LOCATION OF HOLES.

6. REMOVE UPPER HALF.

MARK ALL THE HOLES ON THE TRANSFERRED
LOCATION OF CENTRES. MARK CONTROL CIRCLES ALSO.

7. RESET THE LOWER HALF TO

11/29 Continued

PLACE REFERENCE. SIDE (H2 SIDE) ON EQUAL
HEIGHT SUPPORTS AND SPLIT SURFACE IN VERTICAL
PLANE. ALIGN TO BRING SPLIT SURFACE
IN VERTICAL PLANE AND MARKING
OF REFERENCE SURFACE IN HORIZONTAL PLANE.

8. MARK ON THE SPLIT SURFACE

11/29 Continued

FOR MILLING AREA 375X775 WITH R50
AS PER VIEW-Z ON BOTH LEFT
SIDE AND RIGHT SIDE (CONTOURS
ON LEFT AND RIGHT SIDE ARE DIFFERENT).

9. MARK 4 HOLES DIA 17.5 (M20) AS PER VIEW-Z.
INSPECTION-CHECK MARKING AS PER DRG.

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 12 / 3 ✓

XXX 1
END SHIELD MACHINING 01393701005 00 2 01393701006 00
9250.000

0202-0205

12/29 2035 266 ~~12/29~~ ~~2035~~ ~~266~~ VENDOR SCOPE

1. PLACE LOWER HALF ON SUPPORTS PLACED ON M/C
ROTARY TABLE WITH SPLIT SURFACE TOWARDS
M/C SPINDLE AND FLANGE SIDE
(H2 SIDE) RESTING ON SUPPORTS.
ALIGN AS PER THE SPLIT SURFACE AND CLAMP.
2. DRILL AS PER MARKING 24 HOLES R2320.0222 FLAT DRILL

12/29 Continued

- DIA 32(M36) THROUGH (VIEW-Z). D31.9
3. DRILL AS PER MARKING 6 BLIND HOLES.
DIA 32(M36) AS PER SEC. L-L DEPTH 50.3
(50+0.3 ALLOWANCE) WITH FLAT BOTTOM.
 4. DRILL AS PER MARKING 16 HOLES
THROUGH DIA 26.5 (M30) AS PER VIEW-Z.

12/29 Continued

5. DRILL 4 HOLES DIA 17.5 (M20)
AS PER MARKING & VIEW-Z.
6. MILL AREA 375X775 WITH R50
AS PER VIEW-Z ON BOTH LEFT
& RIGHT SIDE AS PER MARKING WITH DEPTH 2MM.
7. ROTATE THE TABLE BY 180DEG.

12/29 Continued

- AND BRING MARKING OF SURFACE
AS PER VIEW-N PERPENDICULAR TO M/C SPINDLE.
8. MILL AREA 325X300 WITH R50
AS PER MARKING AND VIEW-N TILL CLEANING.
 9. GET MARKED ON THIS SURFACE 4 HOLES D 17.5(M20)
AS PER VIEW-N & ONE HOLE D29.5(M33)
- S GHOSH S K TANDON



CBOM

18.05.2007

Page 13

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

12/29 Continued

ON OTHER SIDE AS PER SEC. A1-A1.

10. DRILL 4 HOLES DIA 17.5 (M20) AS PER MARKING.

MAINTAINING DEPTH 27.5 AS PER VIEW-N.

R2352.0296 C' B' TOOL

TAP 4 HOLES TO M20 TO DEPTH 20.

D29.4/D45

11. DRILL ONE HOLE DIA 29.5 THROUGH

R6304.0041 MANDREL

AND C' BORE TO DIA 45 TILL

12/29 Continued

DEPTH 2 AS PER SEC. A1-A1.

TAP HOLES DIA 29.5 TO M33 AS PER SEC. A1-A1.

12. RESET AND PLACE THE END SHIELD ON ROTARY TABLE

WITH SPLIT SURFACE ON TABLE. ALIGN AS PER

ALIGNMENT POINTS AND SPLIT SURFACE AND CLAMP.

NON FLANGE SIDE (AIR SIDE)

12/29 Continued

TO REMAIN TOWARDS SPINDLE.

13. MILL ONE ALIGNMENT POINT IN THE MIDDLE ON BORE

D542(REFER DETAIL-V) WITH THE HELP

OF END MILL OF APPROX DIA 50MM.CUT TO BE TAKEN

TO DEPTH SO THAT SOME ALLOWANCE IS LEFT FOR

FINISH TURNING OF DIA 542. MEASURE AND RECORD

12/29 Continued

THE DISTANCE FROM THE MIDDLE

OF THIS ALIGNMENT POINT TO THE

SPLIT SURFACE WITH THE HELP OF MICROMETER.

14. MILL AREA 510X400 WITH R125

R6304.0051 MANDREL DIA 40

AT 2 CORNERS TILL CLEANING AS PER MARKING.

15. MILL AREA 620 (310+310)X170

R2352.0321 D'C'B' TOOL D40

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 14

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

12/29 Continued

TILL CLEANING AS PER MARKING.

/D160

16.SPOT FACE D210 AT TWO SIDES AS PER
MAIN VIEW TILL CLEANING.

17. SPOT FACE HOLES DIA 19 TO DIA 35

R2070.0185 PILOT D19/D35

TILL CLEANING AS PER DRG.

18. UNCLAMP & REMOVE FROM M/C.

12/29 Continued

INSPECTION-CHECK DIMENSION AND SURFACE FINISH.

13/29 2045 254

~~2045~~ ~~254~~ ~~254~~

VENDOR SCOPE

1.PLACE LOWER HALF ON M/C

BED PLATE WITH SPLIT SURFACE IN HORIZONTAL
PLANE. ALIGN WITH SPIRIT LEVEL & CLAMPS.

2.TAP 24 HOLES DIA 31.9 TO M36 THROUGH

3.TAP 6 HOLES DIA 31.9 TO M36 AS PER SEC. L-L
TO DEPTH 40.3 (40+0.3 ALLOWANCE).

13/29 Continued

4. TAP 16 HOLES DIA 26.5 TO M30 THROUGH.

5.TAP 4 HOLES DIA 17.5 TO M20 AS PER VIEW-Z.

INSPECTION-CHECK SIZE AND DEPTH OF HOLES.

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 15

/32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

14/29 2045 934

~~00000~~ ~~00000~~ ~~00000~~

BHFL SCOPE

1. COMPLETELY DEBURR AND CLEAN THE TWO HALVES & ROUND OFF CORNER TO R0.5.
2. PLACE LOWER HALF IN VERTICAL POSITION WITH ITS SIDE SURFACES RESTING ON EQUAL HEIGHT SUPPORTS.
3. PLACE UPPER HALF ON LOWER HALF. ALIGN UPPER HALF SUCH THAT MARKING OF ITS REFERENCE PLANE AND

14/29 Continued

VERTICAL CENTRE LINE COINCIDES WITH THAT OF LOWER HALF.
INSPECTION-CHECK ALIGNMENT OF 2 HALVES.

4. ASSEMBLE TWO HALVES TOGETHER WITH BOLTS ITEM 19, 20, 23 & 24 TECH. PACKING AND WASHER ITEM 39 & 40.

R7429.0053 TECH. PACKING

14/29 Continued

5. CHECK FOR ABSENCE OF GAP AT SPLIT SURFACE. INSPECTION-CHECK FOR PROPER ASSEMBLY.

15/29 2035 266

~~00000~~ ~~00000~~ ~~00000~~

VENDOR SCOPE

1. PLACE END SHIELD ON MACHINE BED PLATE WITH EQUAL HEIGHT SUPPORT IN BETWEEN FOR DRILLING AND REAMING OF TAPER HOLE AS AS PER SEC. BB, CC & DD. ALIGN AS PER SPLIT SURFACE AND 6 ALIGNMENT POINTS AND CLAMP.
2. DRILL 2 HOLES D39.5 (D40) AS PER MARKING.
S GHOSH S K TANDON

R6235.0313 MANDREL D19.5/D
445
10.05.2005



CBOM

18.05.2007

Page 16

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

15/29 Continued

AND SEC. BB AND VIEW-Z.

3. C' BORE HOLES D39.5 TO D44 TILL DEPTH 20.
AND TO D64 TILL DEPTH 2MM AS PER SECTION BB.

R6300.0776 MANDREL R'C'B'T
' D39.5/D64

4. ENLARGE AND REAM 2 HOLES TO TAPER

R8321.0130 TAPER PLUG GAUG
E

1:50 PRELIMINARILY AND FINALLY

MAINTAINING D40 AND DIMENSIONS 130.

R2373.0010 TAPER REAMER D3

15/29 Continued

5. DRILL 4 HOLES D29.5 (DIA 30) THROUGH FOR PINS
AS PER SEC. C-C AND MARKING.

0

6. C' BORE HOLES D29.5 TO D34 TILL DEPTH
20 AND TO D51 TILL DEPTH 2 AS PER SEC. C-C.

R6300.0774 MANDREL R'C'B'T
' D29.5/D34

7. ENLARGE AND REAM 4 HOLES TO TAPER 1 IS TO 50
PRELIMINARILY & FINALLY MAINT.D30 & DIM. 13

R8321.0128 TAPER PLUG GAUG
E

15/29 Continued

8. DRILL 2 HOLES D19.5 (D20) THROUGH FOR PINS
AS PER MARKING AND SECTION DD AND VIEW-Z.

R2373.0022 TAPER REAMER D2
0

9. C' BORE D19.5 TO D23 TILL DEPTH 17
AND SPOT FACE TO D44 TILL DEPTH 2MM.

R2350.0457 R'C'B'T' D19.5/
D23

10. ENLARGE AND REAM 2 HOLES

R2373.0027 TAPER REAMER D4
0

15/29 Continued

PRELIMINARILY & FINALLY MAINTAINING D20 AND

D19.5/D44

DIMENSIONS 85.

D19.5/D44

11. DEBURR AND ASSEMBLE TAPER PINS

R8321.0129 TAPER PLUG
GAUGE

ITEM 28 WITH NUT ITEM 34

& WASHER ITEM 39 ASSEMBLE THE TAPER PINS ITEM 29

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 17/32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

15/29 Continued

ASSEMBLE THE TAPER PINS ITEM 30 WITH NUT ITEM 35 AND WASHER ITEM 40.

INSPECTION-

CHECK REAMING OF HOLES AND ASSEMBLY OF PINS.

16/29 2035 156

~~XXXXXXXXXX~~

SHIELD SCOPE

ALTERNATIVELY FOLLOW CNC PROGRAMME NUMBER %
%8021 , %8031 , %8041 , % 8051 FOR MANUFACTURING
THIS COMPONENT ON CNC MACHINE TOOL. COMPONENT SHALL
BE DULY INSPECTED BY QC AFTER COMPLETION OF
OPERATION. & .
ROUGH TURNING:-

16/29 Continued

1. PLACE EQUAL HEIGHT BLOCKS ON M/C TABLE.
PLACE END SHIELD ON BLOCKS WITH REFERENCE
SIDE ON TOP (H2 SIDE.)
2. ALIGN AS PER THE HORIZONTAL AND VERTICAL
ALIGNMENT POINTS OF ONE HALF. MEASURE THE
BEATING OF ALIGNMENT POINTS IN THE BORE D542 OF

16/29 Continued

TWO HALVES WITH THE HELP OF A DIAL INDICATOR.
ALIGN END SHIELD TO BRING THE DIFFERENCE OF
BEATING IN TWO HALVES ACCORDING TO READINGS
TAKEN IN OPERATION 8 SL NO 13
AND OPN 12 SL NO 14. CLAMP END
SHIELD ON M/C TABLE RECHECK THE
S GHOSH S K TANDON



CBOM

18.05.2007

Page 18/32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

16/29 Continued

ALIGNMENT IN ALL PLANES AND REALIGN IF NECESSARY

3. FACE THE CONTACT SURFACE OF STATOR FRAME

DIA 3300/DIA 3080-0.2

TO DIMENSION 52 (48+4 ALLOWANCE) AS PER SEC.

AA (DETAIL-U) MAINTAINING DIMENSION 190 FROM
BEARING CENTRE LINE.

16/29 Continued

4. TURN O.D. TO 3310 (3300+10) AS PER SEC. A-A
LEAVING 5MM ALLOWANCE FOR FINAL M/CING.

5. FACE TO D680(690-10) MAINTAINING DIMENSIONS
475(470+5) AS PER DETAIL-V AND SECTION A-A
LEAVING 5MM ALLOWANCE FOR FINAL M/CING.

6. BORE D542(552-10) MAINTAINING DEPTH 35

16/29 Continued

AS PER SEC. AA AND DETAIL-V

LEAVING 5MM FOR FINAL M/CING.

7. BORE D532(542-10) AS PER DETAIL-V

LEAVING 5MM ALLOWANCE FOR FINAL M/CING.

8. UNCLAMP THE END SHIELD.

RESET THE EQUAL HEIGHT SUPPORT AND REPLACE

16/29 Continued

THE END SHIELD WITH FLANGE SIDE(H2 SIDE)

MACHINE SURFACE RESTING ON EQUAL HEIGHT

BLOCKS. ALIGN AS PER MACHINED SURFACE AND CLAMP.

9. TURN DIAMETER D775(785-10) MAINTAINING

DIMENSION 120(110+5+5) AS PER SEC. AA & DETAIL-V

LEAVING 5MM ALLOWANCE FOR FINAL M/CING.

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 19/32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

16/29 Continued

10. BORE D850(860-10) AS PER SEC. A-A
MAINTAINING DISTNACE 775
LEAVING 5MM ALLOWNCE FOR FINAL M/CING.
11. BORE D790(800-10) AS PER SEC. AA
LEAVING 5MM ALLOWANCE FOR FINAL M/CING.
12. FACE THE OTHER SIDE OF FLANGE SURFACE

16/29 Continued

- MAINTAINING THICKNESS 50
(48+2) OF FLANGE AS PER SEC. A-A.
13. ROUGH TURN BEARING SEATING SURFACEE
LEAVING 5MM ALLOWANCE FOR FINAL M/CING.
INSPECTION-CHECK DIMENSIONS.
 14. UNCLAMP AND REMOVE FROM MACHINE.

17/29 2035 934 ~~XXXXXXXXXX~~ ~~XXXXXX~~ BHEL SCOPE

- 1.MATCH MARK TWO HALVES.
- 2.DISASSEMBLE END SHIELD IN TWO HALVES.
- 3.DEBURR AND CLEAN THE TWO HALVES.
INSPECTION- CHECK MATCH MARKING.

18/29 2035 266 ~~XXXXXXXXXX~~ ~~XXXXXXXXXX~~ ~~XXXXXXXXXX~~ VENDOR SCOPE

NOTE- ALTERNATIVELY FOLLOW CNC PROGRAMME NO. %
FOR MANUFACTURING THIS COMPONENT ON CNC MACHINE
TOOL.COMPONENT SHALL BE DULY INSPECTED BY QC AFTER
COMPLETION OF OPERATION.
FINAL MACHINING OF LOWER HALF END SHIELD:-
1. PLACE LOWER HALF END SHIELD ON
S GHOSH S K TANDON

5
10.05.2005



CBOM

18.05.2007

Page 20

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

18/29 Continued

ROTARY PLATE WITH FLANGE SIDE
(H2 SIDE) RESTING ON SUPPORTS
AND SPLIT SURFACE TOWARDS M/C
SPINDLE. SET ALL CORNERS TO ZERO
ALIGN AS PER SPLIT SURFACE AND CLAMP.

2. FINISH MILL SPLIT SURFACE TO

18/29 Continued

DIMENSIONS 55. USE MICRO MILLING CUTTER.

3. GET THE SLOT FOR RUBBER CORD MARKED
ON SPLIT SURFACE AS PER VIEW-Z.4. MILL RUBBER CORD SLOT ON SPLIT SURFACE 7
WIDE AS PER MARKING MAINTAINING DEPTH 5 & DIMS.
AS PER VIEW-Z, DETAIL-R & T AND SEC. D1-D1R2323.0085 SLOT MILLING CU
TTER D7

18/29 Continued

(REFER TR-4).

R2323.0057 SLOT DRILL D7

INSPECTION- I. CHECK DIMENSIONS & SURFACE FINISH
II. CARRYOUT D.P TEST ON PARTING PLANE
AFTER FINAL MACHINING.

5. UNCLAMP AND REMOVE FROM M/C.

19/29 2035 266

VENDOR SCOPE

ALTERNATIVELY FOLLOW CNC PROGRAMME NUMBER %
FOR MANUFACTURING THIS COMPONENT ON CNC MACHINE
TOOL. COMPONENT SHALL BE DULY INSPECTED BY QC AFTER
COMPLETION OF OPERATION.

FINISH MACHINING OF UPPER HALF.

1. PLACE THE UPPER HALF OF END SHIELD

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 21 / 32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

19/29 Continued

ON ROTARY TABLE WITH FLANGE
SIDE (H2 SIDE) RESTING ON SUPPORTS
AND SPLIT SURFACE TOWARDS M/C
SPINDLE SET ALL CORNER TO ZERO
ALIGN AS PER SPLIT SURFACE AND CLAMP.

2. FINISH MILL THE SPLIT SURFACE

19/29 Continued

TO DIMENSION 55 TO FINISH AS PER DRAWING.
USE MICRO MILLING CUTTER.
INSPECTION-I.CHECK DIMENSIONS AND SURFACE FINISH.
II.CARRYOUT D.P.TEST OF PARTING PLANE.
AFTER FINAL MACHINING.

3.UNCLAMP AND REMOVE FROM MACHINE

20/29 2035 934  BHEL SCOPE

1. COMPLETELY DEBURR AND CLEAN TWO HALVES.
2. ROUND OFF THE CORNER OF SEALING GROOVES
TO R0.5 AS PER SEC. D1-D1.
3. PLACE LOWER HALF IN VERTICAL POSITION
WITH ITS SIDE SURFACES RESTING ON EQUAL
HEIGHT SUPPORTS.

20/29 Continued

4. PLACE UPPER HALF ON LOWER HALF.
ALIGN UPPER HALF SO THAT MARKING
OF ITS REFERENCE PLANE AND VERTICAL
CENTRE LINE COINCIDES WITH THAT OF LOWER HALF.
INSPECTION-I.CHECK ALIGNMENT OF 2 HALVES.
II.CHECK GAP BETWEEN TWO HALVES AT JOININ
S GHOSH S K TANDON



CBOM

18.05.2007

Page 22 / 32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

20/29 Continued

SURFACE. IT SHOULD NOT BE MORE THAN 0.6
(REFER TR- 5).

5. LOOSEN AND SHIFT THE END SHIELD COVER

ITEM 13 ONE MM UPWARDS IN U/HALF.

ASSEMBLE TWO HALVES TOGETHER WITH

TECHNOLOGICAL PACKING AND WITH BOLTS.

R7429.0053 TECH. PACKING

20/29 Continued

ITEM 23 & WASHER ITEM 39 BOLT ITEM 19, 20 & 24
WASHER ITEM 40.

6. CHECK GAP AT SPLIT SURFACE AS PER TR-5. IT

SHOULD NOT BE MORE THAN 0.1

INSPECTION-I.CHECK THE PROPER ASSEMBLY.

II.CHECK GAP AT SPLIT SURFACE AS PER

20/29 Continued

TR-5. IT SHOULD BE LESS THAN 0.1

21/29 2035 156

~~2035~~ ~~156~~ ~~156~~ BHEL SCOPE

REFER CNC PROGRAMMES GIVEN IN OPN. NO. 16/29

FINISH TURNING:-

1. PLACE AND CLAMP 4 NOS. EQUAL HEIGHT

BLOCKS TO SUPPORT AIR SIDE

(NON-FLANGE SIDE) OF END SHIELD.

2. PLACE END SHIELD ON M/C. TABLE WITH AIR

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 23

1

XXX

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

21/29 Continued

SIDE DOWNWARDS.

3. ALIGN AS PER MACHINED SURFACES AND CLAMP.
4. TURN OD TO D3300 AS PER SEC. A-A & DETAIL-U.
5. FINISH FACE STEP D690+0.3 FINALLY MAINTAINING DISTANCE 470+/-0.2 AS PER SEC. A-A & DETAIL-V.
6. TURN RECESS 0.5 DEEP 44 WIDE AT

21/29 Continued

DIA 3156-1 ON FLANGE SURFACE.

7. TURN GROOVE 6 WIDE MAINTAINING DEPTH 6 AT D3122+/-0.5 AS PER DETAIL-U.
8. BORE D552+0.5 FINALLY MAINTAINING DEPTH 35 WITH R5 AS PER DETAIL-V, SEC. A-A.
9. BORE D542-0.5 FINALLY AS PER DETAIL-V.

21/29 Continued

INSPECTION:-CHECK DIMENSIONS AND FINISH.

10. UNCLAMP AND REMOVE THE END SHIELD, PLACE BLOCKS BELOW THE JAWS AND OVERTURN THE END SHIELD AND PLACE THE REFERENCE PLANE ON THE TABLE WITH H2 SIDE DOWN, ALIGN AS PER FINISH MACHINED

R7701.0151 BLOCK FOR JAWS

21/29 Continued

SURFACES AND CLAMP.

11. TURN FLANGE SURFACE MAINTAINING THICKNESS 48-0.3 AS PER SEC. A-A & DETAIL-U.
12. FINISH BORE BEARING HALF RING SEATING SURFACE TO D782.4+0.080/-0.000 MAINTAINING SURFACE FINISH AS PER SECTION A-A.

R7011.0073 PLATE FOR BORE

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 24

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

21/29 Continued

13. BORE D860 AS PER SEC.

A-A MAINTAINING DISTANCE 755.

14. BORE DIA 800 FINALLY AS PER SEC. A-A.

15. FINISH TURN STEP D785+0.3 MAINTAINING DISTANCE
110+0.2 AS PER SEC. A-A AND DETAIL-V.

16. TURN GROOVE 9 WIDE WITH DEPTH 5+0.2

21/29 Continued

WITH R0.5 AT BOTTOM ON D637, CHAMFER 1.5X45DEG.
AT THE CORNERS OF THE GROOVE.(REFER DETAIL-P).

INSPECTION:-CHECK DIMENSIONS AND SURFACE FINISH.

17. UNCLAMP AND SHIFT THE END SHIELD BY

15 MM AS PER DRG.AND TURN THE ECENTRIC GROOVE
8 WIDE WITH D580/D596 AND DEPTH

21/29 Continued

10 AS PER DETAIL-V.

INSPECTION-CHECK DIMENSIONS AND FINISH.

18.UNCLAMP AND REMOVE FROM MACHINE

22/29 2035 935

BHEL SCOPE

1. MARK 80 HOLES DIA 40 AT PCD 3200 AS PER DRG.

2. MARK 6 HOLES DIA 28 ON PCD 3200.

3. MARK 16 HOLES D21 (M24) ON PCD 700 AS PER
DETAIL-V. FOR SEAL RING HOLDER. (REFER VIEW-O).

4. MARK 24 HOLES DIA 10.2 (M12)
ON PCD 830 MATCHING WITH OIL

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 25

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

22/29 Continued

WIPER RING DRG.(SEC. A-A).

5. MARK 4 GROUPS OF 4 HOLES DIA 17.5 (M20) ON PCD 140 AS PER VIEW-X.
6. MARK 4 HOLES DIA 14 (M16) ON PCD 125 FOR SEAL OIL DRAIN & 2 GROUPS OF 4 HOLES DIA 14(M16) ON PCD 110 FOR SEAL OIL SUPPLY AND RING RELIEF OIL

22/29 Continued

INLET IN LOWER HALF END SHIELD AS PER DRG.
IN MILLED AREA (310+310)X170

7. MARK 4 HOLES DIA 14 (M16) ON PCD 145 AND 8 HOLES DIA 14 (M16) ON PCD 160 IN LOWER HALF END SHIELD.
8. MARK 8 HOLES DIA 17.5 (M20)

22/29 Continued

ON PCD 240 IN MILLED AREA 400X510 IN LOWER HALF.

- 8A.MARK 4 HOLES D 10.2(M12) ON PCD 70 & ONE HOLE D 18.63(G 1/2") AS PER DRG.
- 9.MARK 2 HOLES D8 AS PER DETAIL-R & SEC. B1-B1.
- 10.MARK 2 HOLES D8 & 2 HOLE D10.2(M12) AS PER SEC. E-E.

22/29 Continued

- 11.MARK 3 HOLES DIA 8 AS PER SEC. F-F.
 - 12.MARK 2 HOLES DIA 10 AS PER SEC. I-I.
 - 13.MARK 2 HOLES DIA 5 AS PER SEC. J-J.
 - 14.MARK 2 HOLES DIA 14.95 AS PER SEC. C1-C1 & VIEW S IN UPPER HALF (FOR G3/8").
 15. MARK 2 HOLES DIA 8 AS PER SEC. C1-C1.
- S GHOSH S K TANDON



CBOM

18.05.2007

Page 26

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

22/29 Continued

16. MARK 2 HOLES DIA 24.25 (G3/4")
AS PER VIEW X AND SEC. G-G.
INSPECTION- CHECK MARKING.

23/29 2045 254

~~0202~~

~~0205~~

~~0206~~

VENDOR SCOPE

NOTE- ALTERNATIVELY FOLLOW CNC PROGRAMME NO. %
& FOR OPERATION NO. & FOR
MANUFACTURING THIS COMPONENT ON CNC M/C TOOL.
COMPONENT SHALL BE DULY INSPECTED BY QC
AFTER COMPLETION OF OPERATION.

1. PLACE END SHIELD ON M/C BED

R6100.0097 EXTENSION SLEEV

23/29 Continued

PLATE WITH FLANGE SIDE (H2 SIDE)
ON TOP ALIGN AND CLAMP.

E

2. DRILL THROUGH 80 HOLES DIA 40 AT PCD 3200 AS PER
MARKING (2HOLES THE FIRST HOLE ON LEFT SIDE AND
RIGHTSIDE BELOW THE PARTING PLANE OF BOTTOM
HALF IS TO BE DONE LATER).

23/29 Continued

- DRILL 6 HOLES DIA 28 AS PER MARKING.
3. DRILL 4 GROUP OF 4 HOLES DIA 17.5
AS PER MARKING AND VIEW X TO DEPTH 38.
4. TAP 4 GROUPS OF 4 HOLES DIA 17.5
TO M20 TILL DEPTH 30.
5. OVERTURN AND REST THE END SHIELD
S GHOSH S K TANDON



CBOM

18.05.2007

Page 27

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

23/29 Continued

WITH NON FLANGE SIDE
(AIR SIDE) ON TOP. PLACE ON EQUAL
HEIGHT SUPPORTS. ALIGN AND FIX.

6. DRILL 2 HOLES DIA 10 AS PER SEC
I-I (THROUGH) ON LOWER HALF

R2350.0377 CBT D10/D17.25

7. C'BORE 2 HOLES DIA 10 TO DIA 17.25

R2624.0006 TAP PG11

23/29 Continued

(PG 11) TILL DEPTH 13.

8. TAP 2 HOLES DIA 17.5 TO PG 11 TILL DEPTH 8.5

R2350.0378 CBT D5/D17.25

9. DRILL 2 HOLES DIA 5

AS PER SEC J-J (THROUGH) ON LOWER HALF.

10. C'BORE 2 HOLES DIA 5 TO DIA 17.25

(PG11) TILL DEPTH 13.

R2624.0006 TAP PG11

23/29 Continued

11. TAP 2 HOLES DIA 17.5 TO PG 11 TILL DEPTH 8.5

12. DRILL 2 HOLES DIA 24.25 (G3/4")

R2352.0264 CBT D24.25/D38

AS PER VIEW-X, SEC. G-G & MM AND MARKING.

13. C'BORE DIA 24.25 TO DIA 38+0.1

R6304.0034 MANDREL

14. DRILL 24 HOLES DIA 10.2

THROUGH ON PCD 830 AS PER MARKING.

23/29 Continued

15. DRILL 4 HOLES DIA 14 ON PCD

125 TILL DEPTH 25 AS PER MARKING ON LOWER HALF.

16. TAP 4 HOLES DIA 14 TO M16

TILL DEPTH 20 AS PER DRG.

17. DRILL 2 GROUPS OF 4 HOLES D14(M16) TILL DEPTH

20 ON PCD 110 AS PER MARKING ON LOWER HALF.

S GHOSH

S K TANDON

5
10.05.2005



CBOM

18.05.2007

Page 28

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

23/29 Continued

18. DRILL 4 HOLES DIA 14 (M16) ON PCD 145 AND 8
HOLES DIA 14 (M16) ON PCD 160 TILL DEPTH 30 AS
PER MAKRING ON LOWER HALF.
19. TAP 8 HOLES DIA 14 TO M16
AS PER DRG. TO DEPTH 23.
20. DRILL 8 HOLES DIA 17.5

23/29 Continued

- M20 ON PCD 240 TILL DEPTH 27.5
AS PER MARKING ON LOWER HALF.
21. TAP 8 HOLES DIA 17.5 TO M20 TILL DEPTH 20.
22. DRILL 2 HOLES DIA 8 THROUGH
AS PER SEC. B1-B1 & MARKING.
23. DRILL 2 HOLES DIA 15.25 TO DEPTH 34 AS PER

23/29 Continued

- SEC. B1-B1.
24. TAP 2 HOLES DIA 15.25
TO G3/8" AS PER SEC. B1-B1.
25. DRILL 2 HOLES DIA 8 & ONE HOLE D10.2 (M12)
THROUGH AS PER SEC EE AND MARKING.
26. C'BORE 2 HOLES DIA 8 & ONE HOLE D10.2 TO

R2350.0376 CBT D8/D15.25

23/29 Continued

- DIA 15.25 TILL DEPTH AS PER SEC. E-E.
27. C'BORE 3 HOLES DIA 15.25 TO
DIA 40 DEPTH 2 AS PER DRG.
28. TAP 3 HOLES DIA 15.25
TO G3/8" AS PER SEC. E-E.
29. DRILL 3 HOLES DIA 8 THROUGH
S GHOSH S K TANDON

R2350.0419 PILOT D14.5/D30

R2070.0247 PILOT

R2350.0376 CBT D8/D15.25

5

10.05.2005



CBOM

18.05.2007

Page 29

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

23/29 Continued

AS PER MARKING AND SEC. F-F.

30. C'BORE 3 HOLES DIA 8 TO

D15.25 TO DEPTH 22 AND TO DIA 40

R2350.0376 CBT D8/D15.25

31. TAP 3 HOLES DIA 15.25 TO G3/8".

R2070.0247 PILOT

32. DRILL 2 HOLES DIA 8 AS PER SEC. C1- C1

AS PER MARKING.

23/29 Continued

33. C' BORE HOLES DIA 8 TO DIA 30+0.2
TILL DEPTH 11.34. DRILL 2 HOLES DIA 14.95 TILL
DEPTH 65 AS PER SEC. C1-C1 AND MARKING.35. C' BORE HOLES DIA 15.25 TO DIA 40
TILL DEPTH 2MM AS PER SEC. C1-C1.

23/29 Continued

36. TAP HOLES DIA 15.25 TO G3/8" TILL DEPTH 15.

37. DRILL AND TAP 4 HOLES D 10.2 (M12) ON PCD 70
AND 1 HOLE D 18.63 (G1/2") AS PER MARKING & DRG
AND S F 1 HOLE D 18.63 TO D 35 AS PER DRG.
INSPECTION-

CHECK LOCATION AND SIZE OF HOLES.

24/29

2035

934

02020

02020

02020

BHEL SCOPE

1. DISMANTLE THE 2 HALVES.

2. DEBURR AND CLEAN.

S GHOSH

S K TANDON



CBOM

18.05.2007

Page 30

1

XXX

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

25/29

2045

254



VENDOR SCOPE

1. DRILL 2 HOLES DIA 40 AT PCD
3200 (1ST HOLES LEFT AND
RIGHTSIDE BELOW PARTING PLANE IN BOTTOM HALF.)
INSPECTION-

CHECK SIZE AND LOCATION OF HOLES.

26/29

2035

935



BHEL SCOPE

1. MARK 3 HOLES M7X2 ON CORD DIA 542
AS PER SEC HH IN LOWER HALF END SHIELD.
2. MARK 2 HOLES DIA 8 PERPENDICAL
TO HOLES G3/8
AS PER SEC B1-B1 MAINTAINING DIMENSION 20.
3. MARK 2 HOLES DIA 8 AT 35DEG.

26/29 Continued

(MARK THE AXIS OF HOLES DIA 8
AS PER VIEW S ON UPPER HALF).

4. MARK 1 HOLES DIA 12 AS PER SEC. C1-C1
ON UPPER HALF.

27/29

2035

266



VENDOR SCOPE

NOTE- ALTERNATIVELY FOLLOW CNC PROGRAMME NO. %
FOR MANUFACTURING THIS COMPONENT ON CNC M/C TOOL.
COMPONENT SHALL BE DULY INSPECTED BY
QC AFTER COMPLETION OF OPERATION.

1. PLACE LOWER HALF ON M/C ROTARY
TABLE WITH SPLIT SURFACE PERPENDICULAR TO M/C
S GHOSH S K TANDON

R2352.0318 C'B'T' D70/D85



CBOM

18.05.2007

Page 31

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

27/29 Continued

- SPINDLE. ALIGN AS PER MACHINE SPINDLE AND CLAMP. R6304.0048 MANDREL
2. DRILL 3 HOLES DIA 70 (M72X2) THROUGH
AS PER SEC HH & MARKING. (REFER DETAIL-Q). R2621.0147 TAP M72X2
 3. C'BORE HOLES DIA 70
TO DIA 85 MAINTAINING DEPTH 7MM AS PER DRG.
 4. TAP 3 HOLES DIA 70 TO M72X2 TILL DEPTH 40. R8222.0070 PLUG GAUGE

27/29 Continued

5. DRILL 2 HOLES DIA 8 AS PER MARKING & SEC B1-B1.
6. C' BORE PIPE OPENING
DIA 68.1 TO DIA 90.+0.5
TO DEPTH 3.2+0.5 AS PER SEC. M1-M1..
INSPECTION-CHECK AS PER DRAWING. R2352.0319 CBT D68.1/D90
R6304.0049 MANDREL
7. UNLAMP AND REMOVE FROM M/C.

28/29 2035 266

~~2035~~

~~2035~~

~~2035~~

VENDOR SCOPE

1. PLACE UPPER HALF ON ROTARY
TABLE WITH SPLIT SURFACE TOWARDS M/C SPINDLE.
ALIGN AS PER SPLIT SURFACE AND CLAMP.
2. DRILL 2 HOLES DIA 12 TILL DEPTH
5 AS PER SEC. GG & MARKING.
3. UNCLAMP & RESET THE END SHIELD,

28/29 Continued

- SO THAT AXIS OF HOLE DIA 8 AT 35 DEGREE IS
PERPENDICULAR TO M/C.SPINDLE.ALIGN AND CLAMP.
4. DRILL 2 HOLES DIA 8 AS PER SEC. C1-C1
(JOINING HOLES D12 TO D14.95).
INSPECTION-CHECK AS PER DRG.
 5. UNLAMP AND REMOVE FROM M/C.

S GHOSH

S K TANDON

5

10.05.2005



CBOM

18.05.2007

Page 32

32

XXX

1

END SHIELD MACHINING

01393701005 00

2

01393701006 00

9250.000

0202-0205

29/29 2053 934




BHEL SCOPE

1. ROUND OFF SHARP EDGES AND CLEAN.
2. COMPLETELY DEBURR AND CLEAN THOROUGHLY INCLUDING ALL HOLES, OIL PIPE LINES, CHAMBERS TO MAKE THEM FREE FROM CHIPS, OIL ANY FOREIGN PARTICLE.
3. MARK IDENTIFICATION AS PER TR-2.

29/29 Continued

- INSPECTION-1. CHECK AS PER DRG.
2. CHECK FOR CLEANINESS INCLUDING ALL HOLES PIPE LINES, CHAMBERS ETC. FOR ABSENCE OF CHIPS / FOREIGN PARTICLES.



S GHOSH

S K TANDON

5
10.05.2005