


Annexure:I



NOTE :-To be brazed by keeping inductor on top of butt joint of copper flats.