









1. FINISH: PAINT TO SPEC. ES 1213 P1.
GREEN GREY RAL 7009.
2. BOGIE FRAME TO BE HEAT TREATED (STRESS RELIEVING) AFTER WELDING AS PER RDSO SPEC NO VL-SPEC-C (LATEST VERSION)
3. THREE NOS. OF DIA. 6 HOLE AT A, A₂, A₃ AND ONE NOS. OF DIA. 6 HOLE ON EACH AXLE GUIDE BEARING (TOTAL SIX NOS.) AT "C" FOR STRESS RELIEVING. SAME TO BE PLUGGED BY WELDING.

ITEM NO.	QTY	DESCRIPTION	UNIT	QTY	QTY	QTY	QTY
T211/10	10	1209-01-412-010 BOWEL PIN	2	—	—	—	0:05
T211/9	9	1209-01-112-009 BOGIE FRAME MACH. DRAWING	2	—	—	—	3370-0
T211/8	8	—	—	—	—	—	—
T211/7	7	1209-01-412-008 SHIM	24	—	—	—	0:14
T211/6	6	1209-01-412-007 SHIM	24	—	—	—	0:58
T211/5	5	1209-01-412-006 SHIM	8	—	—	—	1:16
T211/4	4	1209-01-312-005 SPRING GUIDE	24	—	—	—	0:18
T211/3	3	1209-01-312-004 SPRING GUIDE	24	—	—	—	1:0
T211/2	2	1209-01-212-003 SPRING GUIDE	8	—	—	—	7:4
T211/1	1	1209-01-212-002 PIVOT	2	—	—	—	2:3
T211/0	—	1209-01-212-001 BOGIE FRAME, WELD ON PARTS 2	2	—	—	—	3450

ITEM NO.	QTY	DESCRIPTION	UNIT	QTY	QTY	QTY	QTY
T211/10	10	1209-01-412-010 BOWEL PIN	2	—	—	—	0:05
T211/9	9	1209-01-112-009 BOGIE FRAME MACH. DRAWING	2	—	—	—	3370-0
T211/8	8	—	—	—	—	—	—
T211/7	7	1209-01-412-008 SHIM	24	—	—	—	0:14
T211/6	6	1209-01-412-007 SHIM	24	—	—	—	0:58
T211/5	5	1209-01-412-006 SHIM	8	—	—	—	1:16
T211/4	4	1209-01-312-005 SPRING GUIDE	24	—	—	—	0:18
T211/3	3	1209-01-312-004 SPRING GUIDE	24	—	—	—	1:0
T211/2	2	1209-01-212-003 SPRING GUIDE	8	—	—	—	7:4
T211/1	1	1209-01-212-002 PIVOT	2	—	—	—	2:3
T211/0	—	1209-01-212-001 BOGIE FRAME, WELD ON PARTS 2	2	—	—	—	3450

ITEM NO.	QTY	DESCRIPTION	UNIT	QTY	QTY	QTY	QTY
T211/10	10	1209-01-412-010 BOWEL PIN	2	—	—	—	0:05
T211/9	9	1209-01-112-009 BOGIE FRAME MACH. DRAWING	2	—	—	—	3370-0
T211/8	8	—	—	—	—	—	—
T211/7	7	1209-01-412-008 SHIM	24	—	—	—	0:14
T211/6	6	1209-01-412-007 SHIM	24	—	—	—	0:58
T211/5	5	1209-01-412-006 SHIM	8	—	—	—	1:16
T211/4	4	1209-01-312-005 SPRING GUIDE	24	—	—	—	0:18
T211/3	3	1209-01-312-004 SPRING GUIDE	24	—	—	—	1:0
T211/2	2	1209-01-212-003 SPRING GUIDE	8	—	—	—	7:4
T211/1	1	1209-01-212-002 PIVOT	2	—	—	—	2:3
T211/0	—	1209-01-212-001 BOGIE FRAME, WELD ON PARTS 2	2	—	—	—	3450

ITEM NO.	QTY	DESCRIPTION	UNIT	QTY	QTY	QTY	QTY
T211/10	10	1209-01-412-010 BOWEL PIN	2	—	—	—	0:05
T211/9	9	1209-01-112-009 BOGIE FRAME MACH. DRAWING	2	—	—	—	3370-0
T211/8	8	—	—	—	—	—	—
T211/7	7	1209-01-412-008 SHIM	24	—	—	—	0:14
T211/6	6	1209-01-412-007 SHIM	24	—	—	—	0:58
T211/5	5	1209-01-412-006 SHIM	8	—	—	—	1:16
T211/4	4	1209-01-312-005 SPRING GUIDE	24	—	—	—	0:18
T211/3	3	1209-01-312-004 SPRING GUIDE	24	—	—	—	1:0
T211/2	2	1209-01-212-003 SPRING GUIDE	8	—	—	—	7:4
T211/1	1	1209-01-212-002 PIVOT	2	—	—	—	2:3
T211/0	—	1209-01-212-001 BOGIE FRAME, WELD ON PARTS 2	2	—	—	—	3450

ITEM NO.	QTY	DESCRIPTION	UNIT	QTY	QTY	QTY	QTY
T211/10	10	1209-01-412-010 BOWEL PIN	2	—	—	—	0:05
T211/9	9	1209-01-112-009 BOGIE FRAME MACH. DRAWING	2	—	—	—	3370-0
T211/8	8	—	—	—	—	—	—
T211/7	7	1209-01-412-008 SHIM	24	—	—	—	0:14
T211/6	6	1209-01-412-007 SHIM	24	—	—	—	0:58
T211/5	5	1209-01-412-006 SHIM	8	—	—	—	1:16
T211/4	4	1209-01-312-005 SPRING GUIDE	24	—	—	—	0:18
T211/3	3	1209-01-312-004 SPRING GUIDE	24	—	—	—	1:0
T211/2	2	1209-01-212-003 SPRING GUIDE	8	—	—	—	7:4
T211/1	1	1209-01-212-002 PIVOT	2	—	—	—	2:3
T211/0	—	1209-01-212-001 BOGIE FRAME, WELD ON PARTS 2	2	—	—	—	3450