

FIELD QUALITY PLAN

FOR


Name of work:- Painting work of annexes/offices/ buildings and other structures inside factory area.



FACTORY CIVIL DEPARTMENT

BHARAT HEAVY ELECTRICALS LIMITED

BHOPAL

 FACTORY CIVIL DEPARTMENT		AUTHORISATION FOR DIFFERENT CATEGORIES OF CHECKS	
Classification of Check		Inspection Authority BHEL	Clearing Authority BHEL
Symbol	Description		
A	Critical	Engineer-in -charge	Sr. Engineer-in -charge
B	Major	Engineer-in -charge	Sr. Engineer-in -charge
C	Minor	Astt. Engineer	Engineer-in -charge

NOTE :

- Quantum of check shall be 100% for all characteristics unless otherwise mentioned in reference documents. Contractors will be responsible for getting the work inspected by inspecting authority after carrying out inspection by themselves as per Field Quality Plan.
- In case of non-conformity, before accepting, clearing agency shall ensure disposition and the same shall be reflected in the log-sheet /protocol.
- For checks where log sheets are not called for, suitable records shall be maintained in the form of log book / protocols.
- Abbreviations used in the column "Type of Check" are
R : Record Verification
M : Measurement
W : Witness
T : Test
V : Visual
- Abbreviations used in the column "Format of Record" are
SR: Site Register
TR : Test Report
- In case of non-availability of inspecting/clearing authority of prescribed level the job shall be performed by higher authorities or the persons authorized by sectional head



BHOPAL
#REF!

FQP- Painting work of annexes/offices/ buildings and other structures inside factory area.

DOC NO: FQP/FCX/21221011

REV NO: NIL

Sr No.	CHARACTERISTICS / ITEM	TYPE OF CHECK	INSTRUMENT	CLASS	QUANTUM/ FREQUENCY OF CHECK	REFERENCE DOCUMENT/ ACCEPTANCE STANDARD	FORMAT OF RECORD	REMARKS
1.0	Acrylic Distemper / Acrylic emulsion paint / Acrylic Smooth exterior paint etc.							
(a)	Packing The material shall be packed in suitable metal or plastic containers.	V	As required	C	100%	As per relevant IS code	SR	Contractor shall submit manufacturer's test certificate.
(b)	Marking 'Each container shall be marked with the following: 1. Name and type of the material 2. Indication of the source of manufacture 3. Volume of the material 4. Lot number or batch number in code or otherwise 5. Month and year of manufacture	V	As required	C	100%	As per relevant IS code	SR	
(c)	Form and Condition The material shall be in the form of a homogeneous paste, free from lumps and skins.	V	As required	C	Each batch of delivery	As per relevant IS code	SR	