BHARAT HEAVY ELECTRICALS LIMITED (A Govt. of India Undertaking)



High Pressure Boiler Plant, Tiruchirappalli 620 014, India (MAINTENANCE & SERVICES DEPARTMENT)

CORRIGENDUM-1

The following text in Open Tender Document shall be read as follows:

SL NO	PAGE No.	EARLIER TEXT	MODIFIED TEXT
1	1	Due date for submission of offer 26.02.2024 / 15:00 Hrs.	Due date for submission of offer 02.03.2024/15:00 Hrs.
2	1	Due date for opening of Techno - Commercial Bid 26.02.2024 / 15:30 Hrs.	Due date for opening of Techno - Commercial Bid 02.03.2024/15:30 Hrs.
3	6 (SCOPE OF WORK)	Total nos. of high mast light maintenance work to be carried out in one years: 67 nos x 2 times =134 nos. Each mast shall be covered once in 6 months from the date of work order. Since 5 nos of High mast lights are taken up for complete overhauling (as indicated in (serv.no.20) one cycle of high mast maintenance works for 5 nos of high mast lights are avoided. Hence Total nos. of high mast light maintenance work to be carried out in one years: (67 nos x 2 times) -5 = 129 nos.	Total nos. of high mast light maintenance work to be carried out in two years: 53nos x 2 times x 2 years = 212 nos. Each mast shall be covered once in 6 months from the date of work order.
4	6 (SCOPE OF WORK)	Periodical Maintenance of High Mast Lighting System: The following activities are to be carried for the periodically once in 6months per year. (i.e 2 time per year) in all the 67 nos High masts.	Periodical Maintenance of High Mast Lighting System: The following activities are to be carried for the periodically once in 6months per year. (i.e 2 time per year) in all the 53nos of High masts.
5	6 (SCOPE OF WORK)	(C) Removing the vegetation grass green plants/ thorny bushes/ tree branches/ unwanted materials etc from the outer precast slab/ gravel yard/ Earth pit of working area 3 X 3 Mtrs of the High mast tower for 60 Nos. of places at 6 times inside and outside of the factory and transporting and dumping the removed rags in the designated place as per the instruction of the substation in-charge.	(C) Removing the vegetation grass green plants/ thorny bushes/ tree branches/ unwanted materials etc from the outer precast slab/ gravel yard/ Earth pit of working area 3 X 3 Mtrs of the High mast tower for 53 Nos. of places at 6 times inside and outside of the factory and transporting and dumping the removed rags in the designated place as per the instruction of the substation incharge.

All the other terms & conditions as published in the tender remain unaltered.