

**Annexure-VII****Minimum Tools & Tackels List to be maintained**

Following bare minimum items are required to be maintained by the Contractor during the WO period . If any items are mispalced / consumed, then the contractor has to provide new ones immediately so that work is not suffered. The availability of the items are to be quaterly verified by contractor.

Sl.No.	Description	Qty.	Unit
1	Ring Spanne (6-32 mm)	4	Set
2	Open Spanner Set (6-32 mm)	4	Set
3	Rachet Spanner	2	Set
4	Electrical insulated Screw driver(+, -, *, )	4	Set
5	Heavy duty Screw driver	4	nos.
6	Electrical tester	8	nos.
7	Test lamp	3	nos.
8	Drilling Machine	2	nos.
9	Cutting kinfe / grass hook	4	nos.
10	Broom	4	nos.
11	Hydro Meter	2	nos.
12	Tool bag	4	nos.
13	Clamp type multimeter(make-Fluke,Hioki,Yokogawa,Meco or Motwane only)	2	nos.
14	Wire Lug Crimping tool	2	nos.
15	Portable welding machine (dry type)	1	nos.
16	Personnel protective equipments (PPE's)		
a	Safety shoes	8	Pairs
b	Helmet	8	nos.
c	Ear plug	8	nos.
d	Safety goggles	4	nos.
e	HT protective gloves (Type Tested)	2	nos.
f	LT protective gloves (Type Tested)	2	nos.

Sign & Seal of  
Party