

Annexure-VIII

Minimum Tools & Tackels List to be maintained

Following bare minimum items are required to be maintained by the Contractor during the WO period . If any items are mispalced / consumed, then the contractor has to provide new ones immediately so that work is not suffered. The availability of the items are to be quaterly verified by contractor.

| Sl.No. | Description | Qty. | Unit |
|--------|---|------|-------|
| 1 | Electrical insulated Screw driver(+, -, *,) | 1 | Set |
| 2 | Electrical tester | 3 | nos. |
| 3 | Spanners (Ring/Open) 7/9/13/17/22 | 2 | set |
| 4 | Test lamp | 1 | nos. |
| 5 | Clamp type multimeter(make-Fluke,Hioki,Yokogawa,Meco or Motwane only) | 1 | nos. |
| 6 | Cutting kinfe / grass hook | 2 | nos. |
| 7 | Broom/Wiper | 3 | nos. |
| 8 | Personnel protective equipments (PPE's) | | |
| a | Safety shoes | 3 | Pairs |
| b | Helmet | 3 | nos. |
| c | Safety goggles | 1 | nos. |
| d | LT/HT protective gloves (Suitable for up to 1000 V AC/DC) | 1 | nos. |

Sign & Seal of
Party