ŝ
\geq
7
V
-
_
N

SSWESSES I	DATE	ALTERED CHECKED	REV	DATE	ALTERED	ADDITIONAL INFORMATION	
	29.07.08				CHECKED	STAUS OF DRAWING	
DRAWING RETRACED.						DISTRIBUTION OF PRINTS	

1. SURFACE PREPARATION FOR SILVER PLATING (BY FABRICATORS):-

- A. WELDED FACES OF CONDUCTOR OR ANY DENT MARK PRESENT ARE TO BE REMOVED EITHER BY SKIM CUT/GRINDING /EMERYING BUT DEPTH OF CUT SHALL NOT EXEED 1.0 mm.
- B. DRILLED HOLES SHALL BE DEBURRED ON BOTH SIDE.
- C. DRILLED END OF THE CONDUCTOR SHALL BE FACED PERPENDICULAR TO THE AXIS OF CONDUCTOR. SILVER PLATING IS TO BE DONE 35 mm FROM LAST HOLE (SEE FIG -1)

2. SPECIAL INSTRUCTION FOR ELECTROPLATERS :-

A. SILVER PLATING TO BHEL STANDARD 'BP 0673697/REV.00' SILVER PLATING TO BE MINIMUM 13 MICRON SILVER OR AS SPECIFIED ON CUSTOMERS SPECIFICATION WHICH EXCLUDES THIKNESS OF COPPER STRIKE AND DOUBLE ZINCATE TREATMENT FIG -1 TO BE FOLLOWED FOR SILVER PLATING OF SURFACE IF SPECIFIED ON DRAWING.




FIG - 1

3. PRECAUTIONS AFTER SILVER PLATING:-

- A. <u>PROTECTIVE COATING ON PLATED SURFACE</u>: SILVER PLATED SURFACE SHOULD BE COVERED BY COTTON TAPE IMMEDIATELY AFTER PLATING (BY ELECTROPLATERS).
- B. WHILE DOING WELDING, PRECAUTIONS TO BE TAKEN SO THAT SILVER PLATED SURFACE IS NOT DAMAGED (BY FABRICATORS).
- C. COTTON TAPE SHOULD NOT BE REMOVED AT ANY STAGE IN THE SHOP. THIS WILL BE REMOVED AT SITE BEFORE MAKING BOLTED JOINTS.

6	· ·		/			NAME	SIGN		DATE
風	म्य हैं एल्ल	BHARAT	BHARAT HEAVY ELECTRICALS LTD.			VISHAL		2	29,07.08
HILEE RUDRAPUR				CHD	P.SINGH		2	29.07.08	
		1.1	KUDKAFUK			RK LAL		2	29.07.08
DEPT.	ECC		SCALE N.T.S.	Wt. [Kg]	REF. TO ASSY. DRG.			ITEM No	
TITLE	GEN I	GEN. INSTRUCTION FOR SILVER PLATING			DRAWING NO.				REV.

GEN. INSTRUCTION FOR SILVER PLATING ON ALUMINIUM CONDUCTOR & FLEXIBLE

4 541 00 01 025

11

SHEET NO. -02

NO. OF SHEETS -03