

## **SPECIAL INSTRUCTIONS**

- 1. Crane / JCB/ gas cutting/ labour deployment permission will be given if necessary for lifting the sold materials (Request letter to be submitted at least one day before the date of delivery). Kindly note that all expenses for the above will be borne by the buyer. Buyers need to deposit photocopy of Aadhaar card of the labour at the time of entry to BHEL gate.**
- 2. Gas Cutting of machine bed from the foundation to the transportable condition is under vendor scope and vendor has to bring all equipment's required for cutting the material and all expenses to be borne by the vendor.**
- 3. Vendor has to cut the machine bed completely and taking the material will be considered as completion of lot.**