Bharat Heavy Electricals Limited Ramachandrapuram : : Hyderabad – 502032 M&S – DIVISION SCOPE OF WORK (ANNEXURE-I)

Tender No.: M&S/P&S/2021/14, Dt.: 17.07.2021

Name of Work: Labour Contract for Refractory Works in Common workshop.

DESCRIPTION OF WORK:

Sl. No.	Activities to be done	Unit	Qty.	Vendor's Acceptance
1	Salt Bath Furnace (08-1022) Removal of damaged bricks and	Nos.	03	
	crucibles and Placing of new crucibles and brick linings with the			
	help of Fire clay and Fire crete.			
2	Ceramic Lining and Heating Element Holding Bricks fixing in 08-	Sq.Mtr.	50	
	1008A, 08-1026, 08-1029, 08-1031 and 08-1032 Furnaces.			
3	Bogie Type Heat Treatment Furnace (08-1026, 08-1031,08-1605 &	No. of	1400	
	08-1032). Damaged portion of trolley has to be repaired with	bricks		
	trolley side bricks, Standard Fire Bricks, Fire crete and Fire clay.			
4	Miscellaneous works in Remaining Furnaces (08-1008, 08-1045, 08-	Sq.Mtr.	30	
	1023, 08-1024, 08-1036, 08-1028, 08-1037, 08-1040, 08-1041, 08-			
	1491, 08-1008A, 08-1008) Resetting and repairing of refractory			
	brick linings and refixing of heating element in position.			
5	High Speed Salt Bath Furnace (08-1023) removal of damaged bricks	Nos.	02	
	& electrodes and Placing of new brick linings with the help of white			
	heat, Fire clay and Fire crete.			
6	08-1301 and 08-1302 LPG Fired Furnace repair. Complete relining	Sq.Mtr.	35	
	work is to be carried out once in a year for both the furnaces,			
	Furnace arch and bottom brick lining is to be done two times in a			
	year. Damaged portion of Flue channel is to be repaired.			
7	08-1301 & 08-1302 LPG Fired Furnace Door Lining work. Door lining	Nos.	25	
	with the help of Insulation brick, Standard Fire Bricks Fire clay and			
	Fire Crete. Whole to be made in Standard fire Bricks, fire crete and			
	Fire clay.			
8	Any other works as and when is identified by the contract	LS	LS	
	executing officer shall also be carried out by the contractor.			

Note: 1) The above work shall be completed in one year based on priority decided by 08- Shop Maintenance.

²⁾ The Mason arranged by the Contractor should have done similar work earlier.