

NIT 2026OSB030 [Section I(C): List of Indicative Drawings]

CARBON STEEL & ALLOY STEEL HEADERS			P91/P92 HEADERS		
PRODUCT	DRAWINGS DESCRIPTION	DRG NO.	PRODUCT	DRAWINGS DESCRIPTION	DRG NO.
CS HEADER	PGMA : 05-147	1-05-147-01990	COMMON	TOLERANCE DRAWING	1-03-000-00034
CS HEADER	PGMA : 05-137	1-05-137-01989	COMMON	HYDRO DUMMY WELDING DRAWING	2-03-000-00094
CS HEADER	PGMA : 19-701	0-19-701-02620	DRILLING STD	SOCKET SEAT PLAN END DRAWING	1-10-183-01282
CS HEADER	PGMA : 19-702	0-19-702-02560	DRILLING STD	SOCKET SEAT TAPER END DRAWING	1-10-183-01283
CS HEADER	PGMA : 19-753	0-19-753-02590	HEADER	PGMA : 10-174	0-10-174-01951
CS HEADER	PGMA : 19-753	0-19-753-02591	HEADER	PGMA : 10-178	0-10-178-01952
CS HEADER	PGMA : 19-753	1-19-753-02984	HEADER	PGMA : 10-185	0-10-185-01969
CS HEADER	PGMA : 19-763	0-19-763-02593	HEADER	PGMA : 10-274	0-10-274-01953
CS HEADER	PGMA : 19-783	0-19-783-02581	HEADER	PGMA : 10-278	0-10-278-01947
CS HEADER	PGMA : 19-793	0-19-793-02584	HEADER	PGMA : 10-283	0-10-283-01966
P12 HEADER	PGMA : 15-136	0-15-136-00418	HEADER	PGMA : 10-285	0-10-285-01949
P12 HEADER	PGMA : 15-136	2-15-136-00125	HEADER	PGMA : 15-178	0-15-178-00417
P12 HEADER	PGMA : 05-227	0-05-227-00701	HEADER	PGMA : 15-236	0-15-236-00413
P12 HEADER	PGMA : 05-227	1-05-227-01980	HEADER	PGMA : 15-278	0-15-278-00415
P12 HEADER	PGMA : 05-251	0-05-251-00699	HEADER	PGMA : 10-182	1-10-182-01819
P12 HEADER	PGMA : 05-251	1-05-251-01977	HEADER	PGMA : 10-274	1-10-274-01816
P12 HEADER	PGMA : 05-327	1-05-327-01986	HEADER	PGMA : 10-278	1-10-278-01812
P12 HEADER	PGMA : 05-327	1-05-330-01984	HEADER	PGMA : 10-283	1-10-283-01821
P12 HEADER	PGMA : 05-330	1-05-330-01983	HEADER	PGMA : 10-291	1-10-291-01813
P12 HEADER	PGMA : 05-350	0-05-350-00711	HEADER	PGMA : 15-178	1-15-178-00451
P12 HEADER	PGMA : 10-135	0-10-135-01960	TUBE	PGMA : 15-278	1-15-278-00452
P12 HEADER	PGMA : 10-176	0-10-176-01959	TUBE	PGMA : 10-174	2-10-174-00614
P12 HEADER	PGMA : 10-176	1-10-176-01818	TUBE	PGMA : 10-178	2-10-178-00615
P12 HEADER	PGMA : 10-183	1-10-183-01810	ATTACHMENTS WELDING	PGMA : 10-182	1-10-182-01820
P12 HEADER	PGMA : 10-184	0-10-184-01948	ATTACHMENTS WELDING	PGMA : 10-285	0-10-285-01950
P12 HEADER	PGMA : 10-191	0-10-191-01945	ATTACHMENTS WELDING	PGMA : 10-283	1-10-283-01822
P12 HEADER	PGMA : 10-235	1-10-235-01823	ATTACHMENTS WELDING	PGMA : 10-285	1-10-285-01815
P12 HEADER	PGMA : 10-284	0-10-284-01961	INSPECTION NOZZLE & FEC	PGMA : 10-174	3-10-174-09905
COMMON	TOLERANCE DRAWING	1-03-000-00034	INSPECTION NOZZLE & FEC	PGMA : 10-278	3-10-278-09907
HEADER	SOCKET SEAT PLAN END DRAWING	1-10-183-01282	INSPECTION NOZZLE & FEC	PGMA : 10-285	3-10-285-10027
HEADER	SOCKET SEAT TAPER END DRAWING	1-10-183-01283	TUBE AND NOZZLES	PGMA : 10-185	2-10-185-00619
COMMON	HYDRO DUMMY WELDING DRAWING	2-03-000-00094	REDUCER	PGMA : 10-285	3-10-285-10029
			EQUAL TEE	PGMA : 10-285	3-10-285-10098
			ATTACHMENTS	PGMA : 10-285	3-10-285-10099
			INSPECTION NOZZLE & FEC	PGMA : 15-236	3-15-236-02269
			HEADER FLAT END COVER	PGMA : 10-285	4-10-285-06890
			TUBE	PGMA : 10-285	4-10-285-06891
			TUBE	PGMA : 15-236	4-15-236-01462
			TC PAD	PGMA : 15-278	4-15-278-01464