

NIT 2026OSB030 [SECTION IV - List of Quality Documents]

DOC TYPE	DESCRIPTION	DOC REF (LATEST REVISIONS TO BE REFERRED)
STANDARD QUALITY PROCEDURE (SQP) & Quality Control Procedures (QCP)	SQP for Headers and Suction Manifold	SQPPP02
	QCP for fabrication of Pressure Parts (Other than Tubular Products)	QCP001
	QCP for Non-Pressure Parts	QCP002
STANDARD INSPECTION PROCEDURE (SIP)	Visual Inspection except Tublar Products	SIPPPP02
	Hydrostatic Testing of Pressure Parts	SIPPPP04
	Inspection of Header nipples	SIPPPP11
	First of Trials for Tublar Products	SIPPPP12
	Sponge test and Ball test	SIPPPP15
	Colour Codes for Tubes & Pipes	SIPPPP21
	Surface preparation and Painting	SIPPPP22
	Identification and Traceability of Attachments by using Weldable Primer	SIPNP13
	Standard Procedure for Remote Inspection	SIPNP24
CONTRACT QUALITY PLAN (CQP)	CQP for Headers	CQP6647_01-Headers
PAINTING SCHEMES (CS & AS HEADERS)	Project specific painting schemes to be followed	PLC3PS1850-1851 PLC3PS1852-1853
PAINTING SCHEMES (P91/P92 Headers)	Project specific painting schemes to be followed	PLC3PS1850-1851 PLC3PS1852-1853
List of Welding Consumable Suppliers	BHEL Approved list of welding consumable suppliers	WTC_WC_LIST_Welding Consumable