

## NIT 2026OSB034 [SECTION IV - List of Quality Documents]

DOC TYPE	DESCRIPTION	DOC REF (LATEST REVISIONS TO BE REFERRED)
QUALITY CONTROL PROCEDURE (QCP) *	NON- PRESSURE PARTS	QCP002
STANDARD INSPECTION PROCEDURE (SIP)	PROCEDURE FOR VISUAL INSPECTION OF NON PRESSURE PARTS	SIPNP06
PAINTING SCHEME**	STANDARD PAINTING SCHEME	SIPPP22 Rev 07

\* Latest Revision

\*\* Standard BHEL painting scheme is provided. Project specific painting scheme will be provided along with POs.