

NIT 2026OSB072 [Section I (C): List of Indicative Drawings]

RATE SCHEDULE	DU CODE	DESCRIPTION	DRAWING NOS	QTY	WT (KGS)
RS01	F58011CQ312001	CYCLONE ASSEMBLY	1-CQ-312-00001	1	38991.69
			3-CQ-312-00001		
			2-CQ-312-00001		
			3-CQ-312-00002		
			3-CQ-312-00003		
			2-CQ-312-00002		
			3-CQ-312-00004		
			2-CQ-312-00003		
			2-CQ-312-00004		
			3-CQ-312-00005		
			3-CQ-312-00006		
			2-CQ-312-00005		
			3-CQ-312-00007		
	F58011CQ332001	LOOPSEAL ASSEMBLY	0-CQ-332-00001	1	41438.74
			3-CQ-332-00008		
			3-CQ-332-00009		
			3-CQ-332-00010		
			3-CQ-332-00011		
			3-CQ-332-00012		
			3-CQ-332-00013		
			3-CQ-332-00014		
			3-CQ-332-00015		
			2-CQ-332-00006		
			3-CQ-332-00016		
			3-CQ-332-00017		
			3-CQ-332-00018		
			3-CQ-332-00019		
			3-CQ-332-00020		
			3-CQ-332-00021		
			3-CQ-332-00022		
			3-CQ-332-00023		
			3-CQ-332-00024		