

NIT 2026OSB060 [Section I (C): List of Indicative Drawings]

PRODUCT	DRAWINGS DESCRIPTION	DRG NO.
LINKS	Links Indicative Drawing-1 SH Connecting Pipes -S01	0-12-850-03617
LINKS	Links Indicative Drawing-2 Arrangement of Furnace Side Riser Pipe F-21-1	1-07-315-01314

Note : The drawings indicated are just for reference to understand the basic work content and arrangement.
Actual drawing will be issued during PO placement.