

ANNEXURE-B

LT PVC CONTROL CABLES	$P = P_o + CuF(Cu-Cu_o) + CCFCu(CC-CC_o) + FeF(Fe-Fe_o) + AlF(Al-Al_o)$
------------------------------	---

FACTORS FOR COPPER CONDUCTOR LT PVC UNARMoured CABLES:					
S NO.	ITEM DESCRIPTION	Variation Factor for Copper (CuF)	Variation Factor for Polymer (CCFCu)	Variation Factor for Armour (FeF)	Variation Factor for Armour (AlF)
1	1.1kV 2C -1.5 CU UNARMoured	0.026	0.118	0	0
2	1.1kV 3C -1.5 CU UNARMoured	0.039	0.121	0	0
3	1.1kV 5C-1.5 CU UNARMoured	0.065	0.157	0	0
4	1.1kV 7C-1.5 CU UNARMoured	0.091	0.179	0	0
5	1.1kV 12C-1.5 CU UNARMoured	0.157	0.249	0	0
6	1.1kV 5C-2.5 CU UNARMoured	0.117	0.187	0	0
7	1.1kV 12C-1.5 CU ARMoured	0.157	0.277	0.289	0