



15219002503

12	12
----	----

1. SHUTTER OPERATION SHOULD BE CHECKED WITH A TEST FINGER AS PER SKETCH "X" BY INSERTING AND WITHDRAWING IT CENTRALLY.



SKETCH 'X'

[illegible][illegible][illegible]

THE INFORMATION ON THIS DOCUMENT IS THE PROPERTY OF BHARAT HEAVY ELECTRICALS LIMITED. IT MUST NOT BE USED DIRECTLY OR INDIRECTLY IN ANY WAY DETRIMENTAL TO THE INTEREST OF THE COMPANY.