

Handling and storage of coated steel products

Must be pasted on all packets clearly visible from outside

For longer life/durability after application, no wastage/damage of coated steel products below handling and storage guidelines are very important.

Handling

- 1) Use nylon/fiber felts for Handling. Do not use steel Wire rope/chains lifting /downloading / Moving
- 2) Use cushioning (wood /rubber) at bottom of & secure lashing & dunnaging **while** transportation.
- 3) Do not transport materials with water/chemicals/vegetables / animals/cement....
- 4) Unload carefully; avoid any packing damages due to unloading/handling.
- 5) If received wet & with damaged packing, Unpack, dry & repack.

Storage

- 1) Store materials on wooden support well over the flat & clean dry floor & temperature below 50°C.
- 2) Do not store materials on wet, damp, muddy floors /lands **directly**. If no option, use about 2 feet steel/ wooden platforms over such places for storing for only for few days.
- 3) Store in well ventilated, dry & protected from rain godowns/shades.
- 4) After Unpacking use materials within couple of days & balance materials remains if any, repack and store for further use.
- 5) Store away from chemicals / cement & any wet materials.