ANNEXURE-I BHARAT HEAVY ELECTRICALS LIMITED RAMACHANDRAOURAM::HYDERABAD-32 **SCOPE OF WORK** work: "Maintenance of Earth Pits inside factory & Loading & Unloading of Fuels, Lube Oils, sludges at 6 MW DG set". Earth Pits - 2 USW Sno Activity 1 Watering of earth pit using Hose pipe or any other way depending on the requirement. 2 Cleaning of area surrounding earth pit, including grass cutting 3 Rust cleaning of earth electrodes and change of nuts and bolts 4 Painting and numbering of earth pits 5 Filling of earth pit with coal and salt 6 Measurement of earth resistance value 7 Digging of earth pit chambers Loading, Unloading - 2USW Activity Sno Movement of Lube oil, transformer oil, DM water etc., using Fork lift to different locations 1 inside BHEL and also to TSTRANSCO substation. 2 Movement of batteries, spares, other materials, etc. using battery truck. 3 Decanting of HFO Tanker 4 Decanting of HSD oil 5 Sludge removal at Lube oil separator 6 Leftover HSD removal @ Tank area 7 Cooling tower cleaning 8 Cleaning of intake filters 9 Cleaning of waterdrop eliminator

SIGNATURE&SEAL OF CONTRACTOR

10 Other related works pertaining to DPH.