

## INSPECTION REQUIREMENTS FOR TENDERED ITEMS

| Item Sl. No. | MATERIAL CODE | DESCRIPTION                           | QTY     | UNIT |
|--------------|---------------|---------------------------------------|---------|------|
| 1            | OE9756110015  | SHELL PARTS ALONG WITH LINER-FA SILO1 | 69,552  | KG   |
| 2            | OE9756110023  | SHELL PARTS ALONG WITH LINER-FA SILO2 | 69,552  | KG   |
| 3            | OE9756110031  | COLUMNS OF FA SILO 1                  | 110,909 | KG   |
| 4            | OE9756110040  | COLUMNS OF FA SILO 2                  | 76,262  | KG   |
| 5            | OE9756110058  | MISCELLANEOUS PARTS OF FA SILO1       | 106,676 | KG   |
| 6            | OE9756110066  | MISCELLANEOUS PARTS OF FA SILO2       | 71,116  | KG   |
| 7            | OE9756132019  | PF BEAMS - GROUP 1 -FA PIPE RACK(UV)  | 125,252 | KG   |
| 8            | OE9756132027  | PF BEAMS - GROUP 2 -FA PIPE RACK(UV)  | 126,544 | KG   |
| 9            | OE9756132035  | PF BEAMS - GROUP 3 -FA PIPE RACK(UV)  | 100,278 | KG   |
| 10           | OE9756132043  | PF BEAMS - GROUP 4 -FA PIPE RACK(UV)  | 107,730 | KG   |
| 11           | OE9756132051  | COLUMNS OF FA PIPE RACK(UV) -MAITREE  | 142,791 | KG   |
| 12           | OE9756132060  | PF GALLERY AND BRACINGS -PIPE RACK UV | 104,002 | KG   |

**Notes:** Inspection shall be carried out as per the below mentioned quality plans, wherever applicable.

**MAIT:C & AHP: R4R5-R4R6**

**MAIT:AHP SILO: R4R5-R4R6**

**PS: MAIT:PG: R676 & R4R5**

Inspection shall be organised by vendor using any of the following customer approved TPI agencies.

- a) TUV SUD South Asia
- b) Bureau Veritas India Limited (BVIL)
- c) Quality Evaluation & System Team Pvt Ltd.
- d) IR Class system and solutions pvt. Ltd.
- e) RITES
- f) TUV Rheinland (India) Pvt. Ltd.

The offer shall be inclusive of the cost of all the inspection and certification charges by the TPIA.  
No separate inspection charges shall be quoted.