



ISO 9001:2008, 14001:2004,
50001:2011 & OHSAS 18000
MAHARATNA COMPANY

MATERIAL MANAGEMENT (PURCHASE)
CENTRAL FOUNDRY FORGE PLANT, BHEL HARDWAR
RANIPUR, HARIDWAR (INDIA) – 249403
Phone No. +91-1334-285533/281299, FAX No. 225892
e-mail : anuragkk@bhel.in; kumar.surendra@bhel.in

Tender Enquiry No. 201900161 (Event ID 40002)
TCMOU:BHEL/CFFP/MM/ TCMOU/FF1135189021/01
SCOPE OF THIRD PARTY INSPECTION:

1. The inspection is to be carried out as per the ordered specification ensuring original manufacturer's packing, Original manufacturer test certificates etc as per specification and the linkage.
- 2.
3. The material should be identified as per the specification like original manufacturer's name, Batch/lot no, Net weight, material name. The material should be packed as per specification and sealed by the inspection agency. The seal details should be mentioned in the third party inspection report.
4. The test certificate should contain the complete witnessing of the chemical analysis of material as per IS1472 for nos of test required in a lot and their testing methodology for evaluating nos of element required by the material specification, size verification as per P.O. Specification, purchase order no, Batch/lot no of material, seal details of the inspector along with corresponding packing (packing list).

(Signature and Stamp of Vendor)